

(21)



HubN_52522133_220525140400.jpg

Created: Wed 25 May 14:04 2022

Fuel supply from on board service tank. No bulk feed connected

(22)



HubN_52522133_220525140410.jpg

Created: Wed 25 May 14:04 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity

(23)



HubN_52522133_220525140423.jpg

Created: Wed 25 May 14:04 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity

(24)



HubN_52522133_220525140533.jpg

Created: Wed 25 May 14:05 2022

Filter system installed outside the bund area

(25)



HubN_52522133_220525140544.jpg

Created: Wed 25 May 14:05 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity

(26)



HubN_52522133_220525140742.jpg

Created: Wed 25 May 14:07 2022

Filter system installed outside the bund area

(27)



HubN_52522133_220525140812.jpg

Created: Wed 25 May 14:08 2022

Filter system installed outside the bund area

(28)



HubN_52522133_220525141240.jpg

Created: Wed 25 May 14:12 2022

Shut off valve outside bund area. All tank shut off valve to be fire safe.

(29)



HubN_52522133_220525141317.jpg

Created: Wed 25 May 14:13 2022

All shut off valve to be fire safe valves

(30)




HubN_52522133_220525141342.jpg

Created: Wed 25 May 14:13 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity

(31)



HubN_52522133_220525141450.jpg

Created: Wed 25 May 14:14 2022

Plug point in zone 2 area.

(32)



HubN_52522133_220525141506.jpg

Created: Wed 25 May 14:15 2022

Plug point in zone 2 area.

(33)



HubN_52522133_220525141535.jpg

Created: Wed 25 May 14:15 2022

Plug point in zone 2 area.

(34)



HubN_52522133_220525141559.jpg

Created: Wed 25 May 14:15 2022


Area under tank to be bund. Bund volume to be 110% of stored capacity



HubN_52522133_220525133355.jpg

Created: Wed 25 May 13:33 2022


Comment header for all bulk storage tank. Each tank to be equipped with its own vent pipe.



HubN_52522133_220525133601.jpg

Created: Wed 25 May 13:36 2022


Diesel supply & return line densco wrap damage. Pipe corroded.



HubN_52522133_220525135249.jpg

Created: Wed 25 May 13:52 2022

Vent pipe reticulated to next generator room.



HubN_52522133_220525135325.jpg

Created: Wed 25 May 13:53 2022

All valve in bund area to fire safe valved

(5)



HubN_52522133_220525135358.jpg

Created: Wed 25 May 13:53 2022

Filtration system outside the bund area. Fuel leak can cause a pool fire.

(6)



HubN_52522133_220525135449.jpg

Created: Wed 25 May 13:54 2022

Filtration system outside the bund area. Fuel leak can cause a pool fire.

(7)



HubN_52522133_220525135506.jpg

Created: Wed 25 May 13:55 2022

Shut off valve to be in bund area. Valve to be fire safe valves

(8)



HubN_52522133_220525135538.jpg

Created: Wed 25 May 13:55 2022

Filter system installed outside the bund area. Plug point in zone 2 area.

(9)



HubN_52522133_220525135712.jpg

Created: Wed 25 May 13:57 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity

(10)




HubN_52522133_220525135717.jpg

Created: Wed 25 May 13:57 2022

Piping color to be silver & banded with correct sulfur content

(11)



HubN_52522133_220525135742.jpg

Created: Wed 25 May 13:57 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity

(12)



HubN_52522133_220525135823.jpg

Created: Wed 25 May 13:58 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity.

(13)




HubN_52522133_220525135833.jpg

Created: Wed 25 May 13:58 2022

Piping color to be silver & banded with correct sulfur content

(14)



HubN_52522133_220525135838.jpg

Created: Wed 25 May 13:58 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity

(15)



HubN_52522133_220525135918.jpg

Created: Wed 25 May 13:59 2022

Filter system installed outside the bund area. Plug point in zone 2 area.

(16)



HubN_52522133_220525135927.jpg

Created: Wed 25 May 13:59 2022

Filter system installed outside the bund area

(17)



HubN_52522133_220525140016.jpg

Created: Wed 25 May 14:00 2022

Filter system installed outside the bund area

(18)



HubN_52522133_220525140025.jpg

Created: Wed 25 May 14:00 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity. Plug point in zone 2 area.

(19)




HubN_52522133_220525140037.jpg

Created: Wed 25 May 14:00 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity. Plug point in zone 2 area.

(20)



HubN_52522133_220525140044.jpg

Created: Wed 25 May 14:00 2022

Area under tank to be bund. Bund volume to be 110% of stored capacity